

FIAT FULLBACK Cab.Doppia 2.4 180 CV LX Silver C.M. S&S Autocarro cabina doppia 4-door - FL666CV

Short Description	Service Type	Start Date	Distance
TAGLIANDO 35000 KM / RMT	Repair and Maintenance	06/07/2018 00:00	19.510 Km
PASTIGLIE FRENO POST. / RMT	Repair and Maintenance	22/11/2018 00:00	35.100 Km
TAGLIANDO 35000 KM / RMT	Repair and Maintenance	26/02/2019 00:00	39.360 Km
SPAZZOLE TERGI ANTERIORE / RMT	Repair and Maintenance	28/05/2019 00:00	41.487 Km
TAGLIANDO 35000 KM / RMT	Repair and Maintenance	15/10/2019 00:00	59.541 Km
PASTIGLIE FRENO POST. / RMT	Repair and Maintenance	15/10/2019 00:00	59.541 Km
TAGLIANDO 35000 KM / RMT	Repair and Maintenance	10/08/2020 00:00	77.100 Km
PASTIGLIE FRENO POST. / RMT	Repair and Maintenance	10/08/2020 00:00	77.100 Km
FRENI	Repair and Maintenance	31/12/2020 00:00	93.150 Km
CLIMATIZZAZIONE / RISCALDAMENTO	Repair and Maintenance	15/04/2021 00:00	100.398 Km
Olio motore	Repair and Maintenance	15/04/2021 00:00	100.398 Km
TRASMISSIONE	Repair and Maintenance	23/04/2021 00:00	100.859 Km
DIAGNOSI	Repair and Maintenance	23/04/2021 00:00	100.859 Km
FRENI	Repair and Maintenance	21/07/2021 00:00	111.725 Km
DIAGNOSI	Repair and Maintenance	21/07/2021 00:00	111.725 Km
BOLLETTINO POSTALE CONCESSIONE GOVERNATIVA (REVISIONE)	Repair and Maintenance	06/08/2021 00:00	114.835 Km
DIAGNOSI	Repair and Maintenance	06/08/2021 00:00	114.835 Km
CLIMATIZZAZIONE / RISCALDAMENTO	Repair and Maintenance	30/09/2021 00:00	121.986 Km
DISTRIBUZIONE & SERVIZI	Repair and Maintenance	30/09/2021 00:00	121.986 Km
FRENI	Repair and Maintenance	30/09/2021 00:00	121.986 Km
Olio motore	Repair and Maintenance	30/09/2021 00:00	121.986 Km
DIAGNOSI	Repair and Maintenance	30/09/2021 00:00	121.986 Km